

## PHOTOS OF TREES PROPOSED TO CLEAR (CPS 9937/1)

**Total: 31 trees** (indicated by red arrows), **including:** 10 Acacia trees.

17 York gum trees (including 2 immature York gum trees)

3 Wandoo trees

1 dead tree.

**ID 1 – Photo 1&2:** 7 Acacia trees (5m high), unhealthy with varying proportion of dead matters  
1 Acacia tree (4m)



**ID 2 – Photo 3:** 1 Acacia, unhealthy within proposed drainage area



**ID 3 – Photo 4:** 1 Acacia, unhealthy, within proposed drainage area



**ID 4 – Photo 5:** 1 York gum (5m).



**ID 5 – Photo 7:** 1 York gum (15m), situated in shoulder area



**ID 6 – Photo 8:** 1 York gum, unhealthy, front with poor historic pruning, situated in shoulder area



ID7 – Photo 16, 17: 1 York gum (7 m), near corner, safety concern + 1 dead tree



**ID 8 – Photo 29:** 1 York gum + 1 immature York gum





ID 9 – Photo 28: 2 York gum + 1 Wandoo (7m)



ID 10 – Photo 30: 3 York gum



**ID 11 – Photo 31:** 1 York gum (<6m high) + 1 York gum with multiple stems to the right



**ID 12 – Photo 32:** 1 York gum (7 m), with 6 stems, situated in the central area of proposed drain.



**ID 13 – Photo 33:** 1 York gum (7m high) + 1 immature York gum to the right

**Photo 34:** 1 York gum (5m high), multi stems due to epicormic growth and poor pruning previously



**ID 14 – Photo 35: 1 Wandoo (5m high)**



**ID 15 – Photo 36:** 1 Wandoo + 1 York gum (6m), situated in the central area of proposed drain



Inconsistency between GPS coordinates and the real locations of the trees.







