## Before and after photos of Truxor in action East Kimberley 2024

## 1. Before clearing of weeds in channel

Notice water way channel has minimal flow, weeds impeding flow and the commencement of eutrophication to the channel. Also notice Truxor operator has clear visuals to identify any fauna or flora species within the direct clearing channel.





## 2. Removal of weed cuttings

Notice removal of weed cuttings has left minimal weed material in the waterway, improving water quality and flow immediately.



## 3. Directly after clearing of weeds in channel

Notice minimal disturbance to before and after of the channel bank with minimal sedimentation and erosion to the foreshore area. Also notice the selective removal of the weeds, keeping vegetation along the foreshore areas to ensure bank stability.

