

***Lot 82 Dugdale Rd, Yallingup***

***Images of vegetation at proposed soak sites***



Image 1. Existing soak adjacent to the watercourse, site of proposed Soak 4.



Image 2. Slumping and erosion of the eastern bank. Significant cracks have developed causing the side to collapse.





Image 3. Image taken from site of proposed soak 4 looking north. Vegetation on the left-hand side of the image will not be impacted.



Image 4. Image taken at proposed soak 3 looking south





Image 5. Proposed soak 2 located north of the vegetation in foreground.



Image 6. Tailwater section of proposed soak 1.





Image 7. Existing vehicle crossing on confluence of the two tributaries and meander in the watercourse.