







SITES TO BE EXAMINED




AA DAM #	SITE	SHIRE
121	Buntine	Dalwallinu
-	Footy Dam	Jerramungup
438	Lake Magenta North	Lake Grace
31	Gutha	Morawa
	Canna Dams	Morawa
5001	Mt Cramphorne	Narembeen
41	Knungajin	Nungarin
125	Perenjori Stn	Shire of Perenjori
315	Ballidu	Wongan-Ballidu
83	Wyalkatchem Siding	Wyalkatchem
5006	Bodallin Dam	Yilgarn



AA Dam #	121
Dam Name	Buntine Shire Dalwallinu
Vesting	Shire of Dalwallinu
LAT/LON	-29.98550 116.57240
Scope of Works	<ol style="list-style-type: none"> 1. Main item description <ol style="list-style-type: none"> a. Approx. 2.9ha bitumen catchment needs a 'refresh' b. Approx. 600m of channel clean up from the N/E of bitumen catchment
Specific Conditions, maps, diagrams	



AA Dam #	None		
Dam Name	Footy Dam	Shire	Jerramungup
Vesting	Shire of Jerramungup		
LAT/LON	-33.9541	118.9219	
Scope of Works	<ol style="list-style-type: none"> 1. Main item description <ol style="list-style-type: none"> a. Approx. 900m of channels north b. Silt trap to the east of the mouth of the dam 		
Specific Conditions, maps, diagrams	 		





AA Dam #	438		
Dam Name	Lake Magenta North	Shire	Lake Grace
Vesting	Watercorporation (handover in process)		
LAT/LON	-32.95214645	118.4664226	
Scope of Works	<ol style="list-style-type: none"> 1. Main item description <ol style="list-style-type: none"> a. Approx. 2.69Ha catchment remove saplings, tidy b. Approx. 342m of channel clean up from the N of dam 		
Specific Conditions, maps, diagrams	<p>The map displays a catchment area of 2.69 ha with a perimeter of 851.32 m. A channel is highlighted with a total length of 171.40 m. The map includes a scale bar (0, 50, 100m) and coordinates: Lat: 33.36502° S, Lon: 119.24861° E. A WKID of 4326 is also shown.</p>		

AA Dam #	31		
Dam Name	Gutha	Shire	Morawa
Vesting	Shire of Morawa		
LAT/LON	-28.99230323 115.9444019		
Scope of Works	<p>1. Main item description</p> <ul style="list-style-type: none"> a. Approx. 4.6ha area of earthen catchment to remove debris, tidy, grade or compact to improve water flow b. Approx. 200 m of channel to remove debris, weeds, saplings to improve water flow from Catchment to dam. 		
Specific Conditions, maps, diagrams			
			

AA Dam #	Unknown		
Dam Name	Canna Dams	Shire	Morawa
Vesting	Shire of Morawa		
LAT/LON	-28.8974	115.8586	
Scope of Works	<ol style="list-style-type: none"> 1. Main item description <ol style="list-style-type: none"> a. Approx. 900m of channel clean needs a 'refresh'; remove saplings, tidy 		
Specific Conditions, maps, diagrams	   <p data-bbox="358 1717 532 1759">2nd Dam above</p>		

AA Dam #	5001		
Dam Name	Mt Cramphorne	Shire	Narembeen
Vesting	DWER		
LAT/LON	-31.83100465 118.7107374		
Scope of Works	1. Main item description a. 2x channels approx. 200m each needs a 'refresh'; remove saplings, tidy		
Specific Conditions, maps, diagrams	 		

AA Dam #	41		
Dam Name	Knungajin	Shire	Nungarin
Vesting	Watercorporation		
LAT/LON	-31.13935148	118.2270197	
Scope of Works	<p>1. Main item description</p> <p>a. Approx. 800m of catchment channels that need a 'refresh'; remove saplings, tidy.</p>		
Specific Conditions, maps, diagrams	<p>Approximate area – blue dashes below;</p>  		

AA Dam #	125		
Dam Name	Perenjori Stn	Shire	Perenjori
Vesting	Shire of Perenjori		
LAT/LON	-29.4412	116.2778	
Scope of Works	<p>1. Main item description</p> <ul style="list-style-type: none"> a. Catchment Approx. 8.62ha of channel clean up from the SW b. 900m of drain to connect catchments to dam c. 3.38ha was bitumen catchment to clear and refresh. 		
Specific Conditions, maps, diagrams	<p>8.62Ha catchment – as below only (not the south section – <i>sandy soils</i>)</p>   <p>Drains below; 2x approx. 450m each</p>  		



Perenjori Stn Cont.






Approx. 240m to join more catchments to the bitumen catchment;

Drain;



AA Dam #	315		
Dam Name	Ballidu	Shire	Wongan-Ballidu
Vesting	Shire of Wongan-Ballidu		
LAT/LON	-30.60040842 / 116.777832		
Scope of Works	<ol style="list-style-type: none"> 1. Main item description <ol style="list-style-type: none"> a. Approx. 7.12ha catchment b. Approx. 300m of channels to dam 		
Specific Conditions, maps, diagrams	 		

AA Dam #	83		
Dam Name	Wyalkatchem Siding	Shire	Wyalkatchem
Vesting	Shire of Wyalkatchem		
LAT/LON	-31.186	117.3865	
Scope of Works	<ol style="list-style-type: none"> 1. Main item description <ol style="list-style-type: none"> a. Approx. 1500m of channels to dam 		
Specific Conditions, maps, diagrams	  		

AA Dam #	5006		
Dam Name	Bodallin Dam (ex-railway)	Shire	Yilgarn
Vesting	Watercorporation (Handover to shire in process)		
LAT/LON	-31.39563316 118.8012488		
Scope of Works	<p>1. Main item description</p> <ul style="list-style-type: none"> a. Approx. 60m each side of inlet road off Stephens Rd for clearway; 0.1ha each side of the access road to the dam, in the road reserve b. Maybe in the [mostly] cleared area for turnaround as below c. 0.3ha area for the tank as below; 		
Specific Conditions, maps, diagrams	<p>Access track in blue dotted line below – inc. approx. tank location in blue circle.</p> 