Southern Site - Detail A -



Photos (\$348245):







Comments for S348245: Peg is offset by 1.5m. One tree (shown above) to be removed. Pruning to be done to provide access and allow easier removal of power pole guy-cable.

Northern Site - Detail B -



Photos (S348185):







Comments for S348185: Pruning of branches required behind peg location (pruning up to about 2m behind peg, full height). No pruning required for branches around stay-pole and guy-cable unless advised.