

Attachment 1

Figures




Figure 1 Overview of Approved Clearing Footprint




Figure 2 Requested Amendment Locations to Management Condition 7




Figure 3 Requested Amendment Location Dongara 30-Group to Management Condition 7




Figure 4 Requested Amendment Location Corybas-01 to Management Condition 7




Figure 5 Dongara 30-Group Aerial




Figure 6 Corybas-01 Wellsite Aerial