



Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA299	470	<i>Eucalyptus rudis</i>	Prune		396029.3 6418623	Excellent	N R	Multi trunk

Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA285	495	<i>Eucalyptus rudis</i>	Clear	 <p>The photograph shows a close-up of a tree trunk with a rough, textured bark. A bright pink marker is tied around the trunk. The background shows some green foliage and a dry, grassy ground.</p>	396281.4 6418628	Excellent	N R	2 trunks.


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA227	455	<i>Eucalyptus rudis</i>	Prune		396398.1 6418630	Excellent	R	Multi-trunk. 4 front trunks to be removed only.


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA231	355	<i>Corymbia calophylla</i>	Clear		396434.1 6418632	Excellent	F R	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA232	400	<i>Corymbia calophylla</i>	Clear		396435.2 6418632	Excellent	F R	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA233	580	<i>Corymbia calophylla</i>	Clear		396443.2 6418633	Excellent	F R N	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA233_S	385	<i>Corymbia calophylla</i>	Clear		396443.2 6418633	Excellent	F R	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA234	365	<i>Corymbia calophylla</i>	Clear		396448.5 6418632	Excellent	F R	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA240	875	<i>Corymbia calophylla</i>	Clear		396540.8 6418634	Excellent	F N R	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA242	550	<i>Corymbia calophylla</i>	Clear		396568.5 6418634	Excellent	F R N	

Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA244	735	<i>Corymbia calophylla</i>	Clear		396597.9 6418635	Excellent	F R N	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA245	440	<i>Corymbia calophylla</i>	Clear		396602.7 6418632	Excellent	F R	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA246	595	<i>Corymbia calophylla</i>	Clear		396607.1 6418635	Excellent	F N R	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA191	250	<i>Melaleuca priessiana</i>	Clear		396515.2 6418646	Excellent		Multi-stem


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA193	245	<i>Melaleuca priessiana</i>	Clear		396507.9 6418645	Excellent		Multi-stem


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA194	505	<i>Eucalyptus rudis</i>	Clear		396507.1 6418645	Excellent	R N	


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA197	190	<i>Eucalyptus rudis</i>	Clear		396493.6 6418646	Excellent		Multi-stem


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA205	270	<i>Melaleuca priessiana</i>	Clear		396443.4 6418644	Excellent		One other stem


Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA276	340	<i>Melaleuca priessiana</i>	Clear		396363.4 6418643	Excellent		5 other main stems

Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA255	530	<i>Melaleuca raphiophylla</i>	Prune		396016.2 6418635	Excellent		Multi-stem

Attachment B – Photo Appendix and details of trees to be pruned or cleared – Karnup Road Widening, Hopeland

Tree Tag	Main trunk DBH (mm)	Species	Treatment	Photo	Easting Northing	Condition	BC Tree Type (F=foraging, N=potential nesting, R=roosting)	Comments
KA247	750	<i>Eucalyptus rudis</i>	Clear		395914.3 6418635	Excellent	N R	