

CPS 11191/1 - Map

116°2'7"E

116°2'10"E


116°2'13"E

31°55'21"S

31°55'21"S

31°55'24"S

31°55'24"S




Legend

-  Areas applied to clear
 -  Local Government Authorities
 -  Land Tenure (LGATE_226) - SLIP
- Roads**
-  Main

Copyright Department of Water and Environmental Regulation, 2022. All Rights Reserved. All works and information displayed are subject to Copyright. For the reproduction or publication beyond that permitted by the Commonwealth Copyright Act 1968 written permission must be sought from the Agency.

Disclaimer: This map is used as a generic static output for reference purposes. Information on this map may or may not be accurate, current, or otherwise reliable. While the Department of Water and Environmental Regulation, has made all reasonable efforts to ensure the accuracy of this data, the department accepts no responsibility for any inaccuracies and persons relying on this data do so at their own risk.





1:700
Projection: GDA2020

116°2'7"E

116°2'10"E


116°2'13"E

Helena Valley Lifestyle Village Stage 10 – Trees to be removed					
Tag Number	Species	Notes	Photo	Photo + Trunk diameter	Additional identification Photos
288	Corymbia Calophylla	To be removed due to Infrastructure – Carvan parking bays			

289

Corymbia
Calophylla

To be
removed due
to
Infrastructure
– Carvan
parking bays



290

Corymbia
Calophylla


To be
removed due
to retaining
wall



291

Corymbia
Calophylla



To be
removed due
to retaining
wall



292

Corymbia
Calophylla


To be
removed due
to retaining
wall



293

Corymbia
Calophylla


To be
removed due
to
Infrastructure
– Carvan
parking bays



294

Corymbia
Calophylla


To be
removed due
to
Infrastructure
– Carvan
parking bays



295

Corymbia
Calophylla

To be
removed due
to retaining
wall



304

Corymbia
Calophylla

Damaged by
Water Corp
to be
removed as it
is sitting over
the sewer
line



318

Corymbia
Calophylla


To be
Removed
due to sewer
location



320

Corymbia
Calophylla

To be
Removed
due to sewer
location



325

Corymbia
Calophylla

To Removed
due to Sub
surface
drainage

