

# **CLEARING PERMIT**

Granted under section 51E of the Environmental Protection Act 1986

### PERMIT DETAILS

Area Permit Number: 5847/1

File Number:

2011/006816-1

Duration of Permit:

From 18 January 2014 to 18 January 2016

### PERMIT HOLDER

City of Busselton

# LAND ON WHICH CLEARING IS TO BE DONE

Acton Park Road reserve, Acton Park (PIN 1377001)

### AUTHORISED ACTIVITY

anded

The Permit Holder shall not clear more than 0.5 hectares of native vegetation within the combined area hatched yellow on attached Plan 5847/1(a) and Plan 5847/1(b) and Plan 5847/1(c) and Plan 5847/1(d).

### CONDITIONS

Nil.

M Warnock

MANAGER

NATIVE VEGETATION CONSERVATION BRANCH

Officer delegated under Section 20 of the Environmental Protection Act 1986

19 December 2013

Plan 5847/1(a)







Government of Western Australia Department of Environment Regulation


WA Crown Copyright 2002

Plan 5847/1(b)







Plan 5847/1(c)





Plan 5847/1(d)







# **Clearing Permit Decision Report**

Government of Western Australia
Department of Environment Regulation

### 1. Application details

1.1. Permit application details

Permit application No.:

5847/1

Permit type:

Area Permit

1.2. Proponent details

Proponent's name:

City of Busselton

1.3. Property details

Property:

Road reserve (Acton Park)

Local Government Area:

City of Busselton Acton Park Road

Colloquial name:

Clearing Area (ha)

Application

No. Trees

Method of Clearing

For the purpose of:

0.5

Mechanical Removal

Road construction or maintenance

1.5. Decision on application

Decision on Permit Application:

Grant

**Decision Date:** 

19 December 2013

#### 2. Site Information

## 2.1. Existing environment and information

2.1.1. Description of the native vegetation under application

Vegetation Description

Vegetation Condition

Mapped Beard Vegetation Association 1136 is described as medium woodland; marri with some jarrah, wandoo, river gum and casuarina (Shepherd et al 2001).

Completely Degraded: No longer intact; completely/almost completely without native species (Keighery 1994)

## 3. Assessment of application against clearing principles

Comments

The application is to clear 0.5 hectares native vegetation on the eastern side of the Acton Park Road reserve, Acton Park, for the purpose of upgrading the road.

Consideration has been given to impacts to biodiversity, significant fauna habitat, rare flora, threatened ecological communities, remnant vegetation values, wetlands, watercourses, land degradation, surface water quality, groundwater quality, and flooding. The assessment has found that the clearing under application is not likely to be at variance to any of the clearing principles.

No submissions have been received for this application to clear.

Methodology

GIS Databases:

Busselton 50cm Orthomosaic - Landgate 2007

Hydrography, Linear Pre-European Vegetation

IBRA WA (Regions - Sub Regions)

SAC Biodatasets

### 4. References

Keighery, B.J. (1994) Bushland Plant Survey: A Guide to Plant Community Survey for the Community. Wildflower Society of WA (Inc). Nedlands, Western Australia.

Shepherd, D.P., Beeston, G.R., and Hopkins, A.J.M. (2001), Native Vegetation in Western Australia. Technical Report 249.

Department of Agriculture Western Australia, South Perth.