



Two trees marked both show no obvious hollow points or nesting. Photos taken at the start of Hainge Road heading west to the intersection of McClure Road.



Two trees marked both show no obvious hollow points or nesting. Trees are taken heading west to the intersection of McClure Road.





Two trees marked both show no obvious hollow points or nesting. Trees are taken heading west to the intersection of McClure Road.



One tree marked shows no obvious hollow points or nesting. Trees are taken heading west to the intersection of McClure Road.



One tree marked shows no obvious hollow points or nesting. Trees are taken heading west to the intersection of McClure Road.





Two trees marked showing no obvious hollow points or nesting. Trees are taken heading west to the intersection of McClure Road. These trees are leaning towards the road and are situated within a drain. If pruned the tree will become unstable hence the requirement to remove.