

## Clearing Permit 2018 Crooked Brook road section 3. July-August 2018

Supporting documentation and site survey photographs.

Original application was for a blanket permit for entire road reserve without detailed design provided. Information was subsequently gathered to provide supporting information about vegetation retention in lieu of a detailed design.

Desktop assessment was completed in mid July 2018 using the Environmental Planning Tool provided by WALGA and supported by Shire of Dardanup Intramaps, undertaken by Senior Environment officer, [REDACTED] at Shire of Dardanup.

Results found:

- No records of Significant or Priority Flora, Fauna.
- No evidence of any Potential or Threatened Ecological Communities.
- Low Western Ringtail possum habitat suitability,
- Potential breeding area Jarrah Forest for Carnaby's cockatoo.
- Vegetation has medium connectivity and over 40% vegetation community remaining in IBRA Subregion.

Site Survey: was undertaken on Friday 3<sup>rd</sup> August 2018.

Some potential habitat trees were identified as being appropriate species (*Corymbia calophylla*) and size. Trees were marked on a map that was transcribed and forwarded to the design surveyor for the area, marking potential trees to be retained, and trees suitable for removal. Results of this survey are attached as Crooked brook rd3 Design Draft.

Where possible, the trees included in this draft design will be retained and not cleared as part of the Clearing permit, however a final design is not provided due to time constraints.

Photographs of typical vegetation found along road reserve:

**Photo 1. Facing east. Start of Clearing area.**





**Photo 2 Crooked Brook road facing east**



**Photo 3. Crooked brook Road general road photo facing west near road junction with Mountford road (behind photographer).**



**Photo 4. Some understory south road. Where possible some of this will be transplanted.**

