

# Lily Creek Lagoon Vegetation Photographs

Photo 1



Photograph of Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from the lagoon groyne.

Photo 2



Photograph of Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from the lagoon groyne.

Photo 3



Photograph of excess Cumbungi vegetation on Lily Creek Lagoon. Taken from the lagoon groyne.

Photo 4



Photograph of excess Cumbungi vegetation on Lily Creek Lagoon. Taken from the lagoon groyne

Photo 5



Closer photograph of excess Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from the lagoon groyne.

Photo 6



Another photograph of excess Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from the lagoon groyne.

Photo 7



Photograph of excess Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from the Shire irrigation pump shed.

Photo 8



Photograph of excess Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from Victoria Hwy.

Photo 9



Photograph of excess Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from Victoria Hwy.

Photo 10



Photograph of excess Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from Victoria Hwy.

Photo 11



Photograph of excess Cumbungi and Water Lily vegetation on Lily Creek Lagoon. Taken from Victoria Hwy.