

# Index

## Contents

Project Brief .....	2
Clearing Period .....	2
Calculations .....	2
Location Plan .....	3
Aerial Map .....	4
Photo .....	5
Supporting Documents.....	16

## Project Brief

McClure Road is a main access road for a local produce farm who transports produce daily via McClure and Fawcett Road, Waroona. McClure Road has a build-up of native vegetation with some of that vegetation leaning towards the road and overhanging the road causing concern for road users especially the heavy vehicles which operate along this section of road.

Attached is a letter from the produce farm expressing their concerns over the native vegetation along McClure Road.

## Clearing Period

Funds have been requested as part of the 2020/21 Budget however it is likely the job will re-occur over several financial years. Therefore the clearing period is likely to be September 2020 to September 2024.

## Calculations

The clearing permit is for the full section of road and has been limited to only include the few select trees listed in the below table.

Road Reserve Width:	18m
Seal Width:	6m
Number of Trees:	27
<b>Estimated Hectares:</b>	<b>0.25 Hectares</b>

The native vegetation has been assessed and the table below indicates the Tree ID, Description, Trunk Diameter and Canopy Size.

Tree ID	Description	Diameter	Canopy
5112	<i>Corymbia Calophylla</i>	0.3	7
5113	<i>Corymbia Calophylla</i>	0.5	10
5114	<i>Corymbia Calophylla</i>	0.3	7
5115	<i>Corymbia Calophylla</i>	0.6	12
5116	<i>Corymbia Calophylla</i>	0.4	8
5117	<i>Corymbia Calophylla</i>	0.3	7
5118	<i>Corymbia Calophylla</i>	0.3	7
5119	<i>Corymbia Calophylla</i>	0.3	7
5120	<i>Corymbia Calophylla</i>	0.4	8
5121	<i>Corymbia Calophylla</i>	0.4	8
5122	<i>Corymbia Calophylla</i>	0.3	7
5123	<i>Corymbia Calophylla</i>	0.4	8
5124	<i>Corymbia Calophylla</i>	0.4	8
5125	<i>Corymbia Calophylla</i>	0.4	8
5126	<i>Corymbia Calophylla</i>	0.4	8
5127	<i>Corymbia Calophylla</i>	0.3	7
5128	<i>Corymbia Calophylla</i>	0.3	7
5129	<i>Corymbia Calophylla</i>	0.4	8
5130	<i>Corymbia Calophylla</i>	0.4	8
5131	<i>Corymbia Calophylla</i>	0.4	8
5132	<i>Melaleuca Raphiophylla</i> - Paperbark	0.3	7


<b>5133</b>	<i>Melaleuca Raphiophylla - Paperbark</i>	0.2	6
<b>5134</b>	<i>Melaleuca Raphiophylla - Paperbark</i>	0.2	6
<b>5135</b>	<i>Melaleuca Raphiophylla - Paperbark</i>	0.2	6
<b>5136</b>	<i>Melaleuca Raphiophylla - Paperbark</i>	0.2	6
<b>5137</b>	<i>Corymbia Calophylla</i>	0.5	10
<b>5138</b>	<i>Corymbia Calophylla</i>	0.5	10
<b>5139</b>	<i>Corymbia Calophylla</i>	0.4	8

## Location Plan

McClure Road runs from Fawcett Road to Somers Road.



## Aerial Map






Photo



Tree ID	Direction	Location	Observations
5112	West	South Side	No visible signs of nesting or hollow points.



Tree ID	Direction	Location	Observations
5113	West	North Side	No visible signs of nesting or hollow points.




Tree ID	Direction	Location	Observations
5114	West	North Side	No visible signs of nesting or hollow points.





Tree ID	Direction	Location	Observations
5115 & 5116	West	South Side	No visible signs of nesting or hollow points.





Tree ID	Direction	Location	Observations
5117	West	North Side	No visible signs of nesting or hollow points.



Tree ID	Direction	Location	Observations
5118	West	North Side	No visible signs of nesting or hollow points.



Tree ID	Direction	Location	Observations
5120	West	South Side	No visible signs of nesting or hollow points.





Tree ID	Direction	Location	Observations
5121	West	South Side	No visible signs of nesting or hollow points.



Tree ID	Direction	Location	Observations
5122	West	South Side	No visible signs of nesting or hollow points.





Tree ID	Direction	Location	Observations
5123	West	South Side	No visible signs of nesting or hollow points.





Tree ID	Direction	Location	Observations
5127	West	South Side	No visible signs of nesting or hollow points.