

SER 1

3 tall spindly trees to be removed





Loc 66.9 - 6 trees in this area to be felled. The larger tree's are to be left alone. Limbs of the larger trees may need to be trimmed but will not cause harm or detriment to the viability of the tree.





Loc 56.2 – Approx 5 trees in the area to the left.

