

## ADDITIONAL SUPPORTING INFORMATION –

### Photos of the application area



Figure 1 – Access point to the proposed works site (and clearing area) from an unsealed carpark off Lloyd Drive, Warwick



Figure 2 – Access track to site (established walking path). This one (2-3m) is within the 5m allocated access corridor. Western Power will make efforts to avoid clearing of this *Banksia menziesii*.



Figure 3 – Access track to site (established walking path).



Figure 4 – Access track from south looking north to the car-parking area and access entry into the bushland, with some overhanging branches that may need to be pruned.



Figure 5 – Intersection of the footpath and south western boundary of the site. Impacted tree is visible on the left and surrounding grass trees. The photo on the right is a close up of the tree within the clearing footprint.



Figure 6 – Details some of the surrounding vegetations and trees in the marked polygon area, these include *Eucalyptus marginata* and *Corymbia calophylla* ranging from 3m – 14m.



Figure 7 – Impacted *Eucalyptus marginata* tree to the left and some surrounding grass trees.



Figure 8 - Southern boundary line of the clearing footprint along the existing footpath (looking east) which shows the power pole that needs to be replaced and the existing powerline travelling in a southerly direction. The second photo is of the existing pole (S177236) that will be replaced up close.



Figure 9 - These photos show the existing pole and transformer (S177236) that will be replaced. There is one small dead tree (2m) located close to the power pole. This photo also shows the location of the revegetation area to the east behind the power-pole.



Figure 10 – View south of the existing pole and transformer (S177236) that will be replaced.



Figure 11 – Friends of Warwick Bushland have undertaken replanting of local native species in the area surrounding the proposed works.