

## Attachment 4 - Site Photographs (20 June 2025)



**Photo 1**      *View south from north west corner along the western boundary of the proposed leachate containment pond.*



**Photo 2**      *Vegetation to north of leachate pond (north-west corner) facing north – trees to be retained on boundary.*





**Photo 3**      *Canopy at the north-west corner of the amended development area. No hollows observed.*



**Photo 4**      *South-west corner of the proposed leachate containment pond. No Jarrah or Marri trees observed.*





**Photo 5**      **South-west corner of the proposed leachate containment pond, looking east. Vegetation consists of *Eucalyptus occidentalis*, occasional paperbark and weeds in understorey (*Watsonia* sp.)**



**Photo 6**      **South-east corner of the proposed leachate containment pond with a groundwater bore – looking north east towards existing landfill area.**





**Photo 7**      ***South-east corner of the proposed leachate containment pond, looking west. Weeded understory with introduced Watsonia***



**Photo 8**      ***Sediment basin at the western boundary, looking south towards a groundwater bore.***





**Photo 9**      *Southern boundary of sediment pond. Vegetation consists of paperbarks.*



**Photo 10**      *Southern tip of the amendment area, looking west. No Jarrah or Marri vegetation observed.*





**Photo 11**      *Southern boundary of sediment basin, looking north-east – native vegetation to the east to be retained.*