

HUNTON ROAD SIGHT LINE UPGRADE

Vegetation mapped as *Melaleuca raphiophylla* Woodland/Low Forest Complex

by Sandiford and Barrett 2010.

Understorey highly disturbed as on edge of road and near farmland.




View to south of crossover.



Vegetation to be cleared to the south of crossover.

A few medium sized Marri trees will need to be cleared.



Vegetation to the south to be cleared for sight lines. Large Melaleuca trees will have some large branches pruned, but whole trees will not be cleared.



View to the north from the crossover.



Vegetation to the north of crossover to be cleared for sight lines.