

APPENDIX 01 – PHOTOS



TREE 01 –

Tree 01 is shown above circled in red. From the photo, the established condition of the tree can be noted however, given the tree sits well within the approved building envelope, we are proposing to remove it. Every effort will be made prior to removal of the tree to ensure that any local fauna using it as part of their habitat will be removed from the clearing zone by a registered fauna handler and homed safely in another tree.

TREE 02 –

Tree 03 is shown across various photos below circled in red. From the photos, the condition of the tree is clearly dead so although the tree sits outside the proposed building envelope it seems fair and reasonable to remove the tree in favour of replacing it with a healthy one. Every effort will be made prior to removal of the dead tree to ensure that any local fauna using the tree as part of their habitat will be removed from the clearing zone by a registered fauna handler and homed safely in another tree.





TREE 03 –

Tree 03 is shown across various photos below circled in red. From the photos, the condition of the tree is clearly dead so although the tree sits outside the proposed building envelope it seems fair and reasonable to remove the tree in favour of replacing it with a healthy one. Every effort will be made prior to removal of the dead tree to ensure that any local fauna using the tree as part of their habitat will be removed from the clearing zone by a registered fauna handler and homed safely in another tree.



