





A photograph of a wooded area with a red survey pole and a white text box. The scene is a dense forest with many trees and a ground covered in dry leaves and grass. A silver car is partially visible in the background. A red pole is planted in the ground, and a white box with text is placed next to it. The text reads "37m Trench/Rockbreak to pole".

37m Trench/Rockbreak
to pole



37m Trench/Rockbreak
to Pole

2m Trench

Pillar



Clearing needed here

17m Trench/Rockbreak
On Boundary

Asphalt

17m Trench/Rockbreak
Road Xing



17m Trench/Rockbreak
down boundary

17m Trench/Rockbreak
across road



Clearing Required

